

# Oil Field Environmental Incident Summary

**Incident:** 20131218130731 **Date/Time of Notice:** 12/18/2013 12:52

**Responsible Party:** Rodney Conway

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** PEDERSON 5

**Field Name:** TEMPLE

**Well File #:** 14787

**Date Incident:** 12/17/2013 **Time Incident:** 08:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 158

**Rng:** 95

**Sec:** 18

**Qtr:**

**Location Description:**

**Submitted By:** Rodney Conway

**Received By:**

**Contact Person:** Rodney Conway  
777 MAIN STREET  
SUITE 800  
FORT WORTH, TX 76102

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1.5 Miles

**Distance Nearest Water Well:** 1.5 Miles

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	barrels	1	barrels	0.5	barrels
Brine	10	barrels	8	barrels	8	barrels
Other	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/6/2015

**Clean Up Concluded:** 12/19/2013

**Risk Evaluation:**

none

**Areal Extent:**

12 by 30 feet

**Potential Environmental Impacts:**

Ground was frozen. I snow and water was scraped up and put in burn pit and then sucked out with vac truck and hauled to SW. Remove contaminated soil in spring where crop shows any signs of damage.

**Action Taken or Planned:**

Well shut in. Rubbers replaced. Area cleaned up. Dikes to be put up around well to keep from run off in future.. Land owner present and details worked out.

**Wastes Disposal Location:** Water sent to SWD. Soil removed in spring will be taken to land fill.

**Agencies Involved:**

**Updates**

---

**Date:** 12/18/2013 **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident report, this spill impacted areas off of the well location. Followup is necessary.

---

**Date:** 1/10/2014 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 1/10/14.

No visible signs of damage done by release. Cleanup determined to be adequate.

No followup necessary.